


# HP LaserJet M225

## User 932

<b>Material Picture</b>	
<b>Symptoms</b>	Below pictured HP LaserJet M225 Drum issue
<b>Reasons</b>	932 User have the more work and printing too much paper
<b>Solution</b>	Need to replace with the New printer.

<u>Prepared By</u>	<u>Confirmed By</u>	<u>Approved By</u>
614 Mojahid Hussain	610 Russel. M. Kamarudeen	600 Abdulrahman Y. Alshaikh