Acer Laptop (Retirement Report) Material Picture

Badran ID	0-00119-6
Description	Acer Laptop
Location	HEAD OFFICE
Department	Akrat – 200
Custodian	J026-25 (Glum Mustafa)



Symptoms	As Per the Picture for the Acer laptop is not working
Reasons	Motherboard is damage
Solution	Need to do the retirement.

Prepared By	Confirmed By	Approved By
614	610	600
Mojahid Hussain	Russel. M. Kamarudeen	Abdulrahman Y. Alshaikh